

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-06-15	TECHNICIAN Darren Mann		JOB/O 8575	RDER #	REFERENCE TEXT
FIRST NAME Daniel		LAST NAME Bull	7		
BILLING ADDRESS		10	1.	SERVICE ADDRESS	
709 - 66 WEST CORDOVA ST VANCOUVER, V6B0L2 BRITISH COLUMBIA, CANADA				709 - 66 WEST CORDOVA BUZZER: 5056 VANCOUVER, V6B0L2 BRITISH COLUMBIA, CANADA	
PHONE 604-377-5005				EMAIL mxassistant@gmail.com	

REASON FOR TODAY'S CALL:

The pressure and temperature for "Hot" in my bathroom tub/shower has dropped significantly. The fixture in the bathroom is also a Kohler, single knob.

DESCRIPTION OF WORK PERFORMED:

I replaced the pressure balance and mixing cartridges within the shower valve. Tested and in good working order.

TECHNICIAN RECOMMENDATIONS:

There was hot water crossing over into the cold lines. When I removed the trim the valve was warm which is a good indicator that the crossover was happening at this valve but if the crossover issue persists it could very well be happening in other units as well.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridges - Kohler	\$259.00	\$259.00
0		warranty: <u>Parts</u> - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$259.00
Gwe us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$12.95
			TOTAL:	\$271.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		
		2018-06-15 CUSTOMER SIGNATURE DATE		