

## 609-77 Walter Hardwick Ave. Vancouver, BC V5Y0C6

Phone: 604.727.4484 yaletownplumbing.com

SimplyPlumbing **F** YaletownPlumbing

HST #837181627

| DATE<br>2018-06-25   | TECHNICIAN<br>Darren Mann |                   | JOB/ORDER #<br>8607 |   | REFERENCE TEXT |
|--|---------------------------|-------------------|---------------------|---|----------------|
| FIRST NAME<br>Carolyn & Martin   |                           | LAST NAME<br>Wong | 7                   |   |                |
| BILLING ADDRESS  |                           | 70                | 7,                  | SERVICE ADDRESS   |                |
| 2704 - 610 GRANVILLE ST<br>VANCOUVER, V6C3T3<br>BRITISH COLUMBIA, CANADA |                           |                   |                     | 2704 - 610 GRANVILLE STREE<br>CALL FOR ENTRY: 778-861-30<br>VANCOUVER, V6C3T3<br>BRITISH COLUMBIA, CANADA | 61             |
| PHONE<br>6047233237  |                           |                   |                     | EMAIL carolyn.and.martin.2017@gmail   | .com           |

REASON FOR TODAY'S CALL:

Bathroom faucet - 2 problems: 1/ When the faucet is turned on, water leaks inside the cabinet 2/ When the faucet is shut off, there is still a very slow drip that does not stop (If there is any possibility of an earlier appointment, we would love to take it. Thanks!)

## DESCRIPTION OF WORK PERFORMED:

JUNE25:-The cartridge within the lavatory faucet was leaking through the stem. While I didn?t notice any water on the top of the sink or leaking below, I believe the water was leaking out of the back of the handle onto the top of the sink, and down to the cabinet below. I replaced the cartridge(K35B) within the faucet and tested by filling and draining the sink multiple times with no sign of leaking from above or below the sink. -I tested the kitchen sink and faucet by filling and draining both sides of the sink. I noticed a leak coming from the garburator drain 90, the inside o fry garburator grinding chamber was also starting to deteriorate. -The laundry hoses look to be the original to the building and should be replaced. JUNE26: -I replaced the garburator with a new Waste King 1001 and tested by filling and draining both sides of the sink multiple times. I also ran the dishwasher through a few fill/drain cycles. -I replaced the laundry supply hoses with braided stainless type hoses and tested.

| <b>QTY</b> . | CODE | DESCRIPTION  | UNIT PRICE | PRICE    |
|--------------|------|--|------------|----------|
| 1            |      | Replace Lav Faucet Single Lever Cartridge - Standard | \$159.00   | \$159.00 |
| 1            |      | Supply & Install 1/2HP Waste King 1001 Garburator    | \$279.00   | \$279.00 |
| 1            |      | Replace Laundry Supply Hoses - ADD-ON PRICING        | \$79.00    | \$79.00  |
| ~            |      |  | SUBTOTAL:  | \$517.00 |

PARTS - SUBJECT TO MANUFACTURER'S WARRANTY

## Gwe us Feedback WARRANTY:

Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.

Thank You!

| WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  |
|---|
| INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY     |
| MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND           |
| MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,     |
| SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES |
| RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.                         |
| TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK          |
| CHARGES. E. & O. E.   |
|   |
|   |

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF

2018-06-25

CUSTOMER SIGNATURE

GST (5%):

TOTAL:

\$25.85

\$542.85

DATE