

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-07-13	TECHNICIAN Darren Mann		JOB/OF 8663	RDER #	REFERENCE TEXT
FIRST NAME Easyrent		LAST NAME Admin	7		
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1201 - 1188 HOWE ST RAND: 1.236.333.8068. BUZ#0 <sup>-</sup> VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279				EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL:

-Tub spout diverter not fully diverting water to shower. -Kitchen faucet leaking.

## DESCRIPTION OF WORK PERFORMED:

-I replaced the tub spout with a new Delta pull-down type diverter spout and tested. -The kitchen faucet was leaking from under the handle. I was able to stop the leaking by replacing the seats, springs, and SS ball lever cover. Tested and no other leaks detected.

<b>QTY.</b>	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter		\$159.00
1		Delta Faucet Seats, Springs, Lever Cover		
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$184.00
invoice and tell us how we did.		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$9.20
			TOTAL:	\$193.20
		VE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTI DE DEITED DETERIORATION OR LEAD PIPES EVITIPES CLEAN QUITS AND ANY OTHER DAMAGES.		

	2018-07-13
CUSTOMER SIGNATURE	DATE