



DATE 2018-07-27	TECHNICIAN Darren Mann	JOB/ORDER # 8696	REFERENCE TEXT
FIRST NAME John	LAST NAME Wallace		
BILLING ADDRESS 903 - 1625 HORNBY ST VANCOUVER, V6Z2M2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 903 - 1625 HORNBY ST, BUZZER 0033 VANCOUVER, V6Z2M2 BRITISH COLUMBIA, CANADA	
PHONE 604.568.7243		EMAIL jcwallace@btinternet.com	

REASON FOR TODAY'S CALL:
toilet leaking between tank and bowl.

DESCRIPTION OF WORK PERFORMED:
-I removed the tank and reinstalled with new tank bolts, a tank to bowl gasket, and new braided supply line. During testing I noticed the fillvalve was spraying out of the top. I replaced the fillvalve and tested again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tank To Bowl Gasket - Standard	\$169.00	\$169.00
1	9520164	PRO45B ANTI-SYPH FILL VLV UQ	\$35.00	\$35.00

SUBTOTAL:	\$204.00
GST (5%):	\$10.20
TOTAL:	\$214.20

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

ZC. Wallace

2018-07-27

 CUSTOMER SIGNATURE

 DATE