



HST #837181627

DATE 2018-08-09	TECHNICIAN Darren Mann		JOB/ORDER # 8745	REFERENCE TEXT		
FIRST NAME Alejandro		LAST NAME Romero Gil				
BILLING ADDRESS			SERVICE ADDRESS			
705 - 939 HOMER ST VANCOUVER , V6B 2W6 BRITISH COLUMBIA, CANADA				705 - 939 HOMER ST VANCOUVER , V6B 2W6 BRITISH COLUMBIA, CANADA		
PHONE 604-540-2839			EMAIL alejandro_romero@van	EMAIL alejandro_romero@vanmex.com		

## REASON FOR TODAY'S CALL:

Shower slowly drips from either way, shower or tub spout. Ramses: 604-540-2839 Alejandro: 778.791.2997

## **DESCRIPTION OF WORK PERFORMED:**

-The water would not fully shut off when the handle was in the fully off position. I replaced the cartridge(Temp ii) within the shower valve and tested. -There is a small leak coming out of the connection between the shower 90 and the shower spray head adaptor when the shower is activated. Unfortunately I could not stop this

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II			\$209.00	\$209.00
		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$209.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		GST (5%):	\$10.45	
				TOTAL:	\$219.45	
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

<u> Thank You!</u>

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. CUSTOMER SIGNATURE DATE

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES