



DATE 2018-07-17	TECHNICIAN Darren Mann	JOB/ORDER # 8659	REFERENCE TEXT
FIRST NAME Cyrus	LAST NAME Navabi		
BILLING ADDRESS 1468 SEYMOUR MEWS VANCOUVER, V6Z3E7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1468 SEYMOUR MEWS VANCOUVER, V6Z3E7 BRITISH COLUMBIA, CANADA	
PHONE 604.653.7338		EMAIL cnavabi@qualex.ca	

REASON FOR TODAY'S CALL:

As previously discussed, we have sewer odors from the upstairs master bathroom toilet. Siliconing around the base didn't help. Can you please re-install the toilet as recommended to ensure it is correctly installed/sealed? Thanks.

DESCRIPTION OF WORK PERFORMED:

I lifted the toilet and found there to be no wax ring installed between the Toto floor socket and the floor flange. Without this wax seal it is possible for sewer gases to seep into the home under the right conditions. I installed a wax seal and re-set the toilet. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - DISCOUNTED	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45

_____ 2018-07-17

 CUSTOMER SIGNATURE DATE