

2018-09-14

DATE

HST #837181627

DATE 2018-09-14	TECHNICIAN Darren Mann		JOB/O 8855	RDER #	REFERENCE TEXT Client reference
FIRST NAME Derek		LAST NAME Rowe			
BILLING ADDRESS COMPANY / BILLING NAME 607 - 822 HOMER ST VANCOUVER, V6B 6M3 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS  607 - 822 HOMER ST, BUZZER VANCOUVER, V6B 6M3 BRITISH COLUMBIA, CANADA	
PHONE 778.288.7114				EMAIL derekrowearts@gmail.com	

## REASON FOR TODAY'S CALL:

Guest bathroom toilet fill valve is not functioning properly. The flap is sticking cause intermittent refill. I don't want to mess with it to try adjusting.

## DESCRIPTION OF WORK PERFORMED:

-The fillvalve was not refilling once the tank emptied. I replaced the FillValve and supply line and tested. -I also tested the toilet in the master bathroom and it is in

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard	\$159.00	\$159.00
<i>Q.</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			\$159.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		k page at:  Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFT MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT N		\$7.95
		s from your	TOTAL:	\$166.95
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOW  WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESP  SETTLED BUSTED DETERIORATION OR LEAD PIDES SIXTURES OF EAN OUTS.	AT CHARGES AND ONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES	

CUSTOMER SIGNATURE