

2018-11-13

DATE

HST #837181627

| DATE 2018-11-13 | TECHNICIAN Darren Mann | | JOB/ORDER # 8957 | REFERENCE TEXT Client reference | |
|---|---------------------------|-------------------|--|---|--|
| FIRST NAME Melissa | | LAST NAME Kidd | | | |
| BILLING ADDRESS 1207 - 1077 MARINASIDE CRESCENT VANCOUVER, V6Z2Z5 BRITISH COLUMBIA, CANADA | | | #1207 - 1077 MARIN CYNTHIA(MOM): 1.2 VANCOUVER, V6Z2 | SERVICE ADDRESS #1207 - 1077 MARINASIDE CRESCENT, BUZZER #1577 CYNTHIA(MOM): 1.250.837.1616 VANCOUVER, V6Z2Z5 BRITISH COLUMBIA, CANADA | |
| PHONE 604.562.9951 | | | EMAIL mellykidd@hotmail.c | om | |

REASON FOR TODAY'S CALL:

Replace tub spout.

DESCRIPTION OF WORK PERFORMED:

| I replaced the tub spout with a new Delta pull-down type diverter spout and tested. | | | | | | | | |
|--|---|--|-----------------------------------|----------|--|--|--|--|
| QTY. | CODE | DESCRIPTION | UNIT PRICE | PRICE | | | | |
| 1 | // | Replace Standard Tub Spout Diverter | \$159.00 | \$159.00 | | | | |
| Qo | we us feedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | | SUBTOTAL: | \$159.00 | | | | |
| Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank You! | | k page at: Labour - 1 Year on New Units, 30 DAYS ON REPAIR, VOID AFTER 30 DAY MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABS | ` , | \$7.95 | | | | |
| | | s from your | TOTAL: | \$166.95 | | | | |
| | | MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE | GES AND FOR BROKEN, ITHER DAMAGES | | | | | |

CUSTOMER SIGNATURE