

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-12-04	TECHNICIAN Darren Mann		JOB/ORDER # 9026		REFERENCE TEXT Client reference
FIRST NAME Ruth		LAST NAME Muller	7		
BILLING ADDRESS COMPANY / BILLING NAME 1050 BURRARD ST VANCOUVER, V6Z2S3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1507 - 1251 CARDERO ST BUZ CAIN(TENANT): 604.352.2983 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.328.4186	-			EMAIL rmuller.12@hotmail.com	

REASON FOR TODAY'S CALL:

Leakage surrounding BR toilet. Transition missing.

DESCRIPTION OF WORK PERFORMED:

The leak was coming from between the tank and bowl when flushed. I removed the tank, installed a new tank to bowl gasket and reinstalled the tank with new tank bolts and a new braided supply line. Tested and in good working order. *I wasn?t sure what ?transition? meant but I didn?t notice anything that was missing.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace Tank To E	Replace Tank To Bowl Gasket - Standard				\$169.00
Rung and Tagel and			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00	
Give us Feedback page at: <u>www.yaletownplumbing.com/feedback [1]</u> Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTEL		GST (5%):	\$8.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$177.45		
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2018-12-04					
				CUSTOMER SIGNATURE	DATE		