

HST #837181627

DATE 2019-03-01	TECHNICIAN Darren Mann		JOB/O 9200	RDER #	REFERENCE TEXT 19-0317
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS  2005 - 1483 HOMER ST ZAHID: 604.726.6333 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

## REASON FOR TODAY'S CALL:

Master Bath - Shower: Clip that holds shower at top is broken and is leaking 2nd Bath - Shower: diverter problem

## DESCRIPTION OF WORK PERFORMED:

-I installed the new shower head & hose in the master bathroom and tested. -I installed a new brass nipple and Delta pull-down type diverter spout in the guest bathroom. Tested and in good working order.

QTY.	CODE		UNIT PRICE	PRICE	
1		Replace Standard Tub	\$159.00	\$159.00	
Gwe us Feedback			ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95
Thank You!			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE