

HST #837181627

DATE 2019-03-08	TECHNICIAN Darren Mann		JOB/ORDER # 9228		REFERENCE TEXT 19-0396	
FIRST NAME Advent		LAST NAME Admin				
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1810 - 928 BEATTY ST, BUZ#1136 URSULA: 604.996.2592 604.687.3755 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478	_			EMAIL andrea@adventvancouver.com		

REASON FOR TODAY'S CALL:

Leak under kitchen sink.

DESCRIPTION OF WORK PERFORMED:

The kitchen faucet spray hose was torn internally and could not be repaired. The building also recently sent out a notice recommending that owners replace these faucets as there have been a few leaks in the building caused by them. I installed a new Moen Banbury kitchen faucet and tested.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Discount Labour		\$99.00	\$99.00
1		Moen Banbury Pullout Deck Faucet		\$180.00	\$180.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your		WARRANT	f: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$13.95
		s from your			\$292.95

<u> Thank You!</u>

invoice and tell us how we did.

CUSTOMER SIGNATURE	DATE
	2019-03-08
CHARGES. E. & O. E.	
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA	ATERIALS AND TRUCK
RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT	S AND ANY OTHER DAMAGES
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RI	ESPONSIBLE FOR BROKEN,
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND	THAT CHARGES AND
INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKN	IOWLEDGEMENT IS HEREBY