

Phone: 604.727.4484 yaletownplumbing.com

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2019-04-04	TECHNICIAN Darren Mann		JOB/ORDER # 9289		REFERENCE TEXT Afsaneh	
FIRST NAME Easyrent		LAST NAME Admin				
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 3206 - 688 ABBOTT ST, NO BUZ JAVIER: 778.970.0302 JRIESGO.CA@GMAIL.COM VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.662.3279				EMAIL info@easyrent.ca		

REASON FOR TODAY'S CALL:

Plumbing inspection.

DESCRIPTION OF WORK PERFORMED:

ENSUITE BATHROOM: -When I arrived the tub was clogged and had standing water in it. When the lavatory sink was run it would back up into the tub. I used the PowerSpin drain snake to remove hair through the tub and lavatory drains and tested them both. -The toilet seems to be flushing normally and the supply line is braided stainless with no signs of wear. -The lavatory faucet supply lines are braided stainless and showing no signs of wear. GUEST BATHROOM: -The tub and lavatory drains are flowing freely. -The toilet seems to be flushing normally and the supply line is braided stainless with no signs of wear. -The lavatory faucet supply lines are braided stainless and showing no signs of wear. KITCHEN: -I filled and drained the kitchen sink. The drain is flowing freely, and I saw no sign of leaking. -I removed the dishwasher kickplate to allow access to the underside of the machine and ran it through a short fill drain cycle. There were no signs of leaking and the waterline is hardpiped in Wirsbo and showing no signs of wear. -The copper supply lines to the kitchen faucet are in contact with a metal that is causing them to corrode. This could cause pinholes to develop in these lines which would leak even when the faucet is not in use. Because these copper lines are integral to the faucet the faucet will have to be replaced. LAUNDRY: The laundry supply hoses are black rubber and appear to be the original to the building. It is recommended that these supply hoses by replaced every 5-7 years. Given the fact the building is now 12 years old I suggest replacing these hoses.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00
<i>Q.</i>		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
			TOTAL:	\$145.95
		We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED BUSTED DETERIORATION OR LEAD PIPES FIXTURES OF AN OUTS AND ANY OTHER DAMAGE	s	

CUSTOMER SIGNATURE

2019-04-04