

HST #837181627

DATE 2019-05-14	TECHNICIAN Darren Mann		JOB/ORDER # 9392		REFERENCE TEXT Client reference
FIRST NAME Robyn		LAST NAME Tucker-Peck			
BILLING ADDRESS COMPANY / BILLING NAME 1005 - 590 NICOLA STREET VANCOUVER, BC, V6G 3J8 BRITISH COLUMBIA, CANADA			#100 VAN	VICE ADDRESS 5 - 590 NICOLA ST BUZ#1 COUVER, BC, V6G3J8 ISH COLUMBIA, CANADA	
PHONE 604-336-2433			EMA robyr	IL ntuckerpeck@gmail.com	

## REASON FOR TODAY'S CALL:

The toilet is slowly filling up each time with a loud clicking noise. The kitchen sink spray portion of the tap is not spraying.

## **DESCRIPTION OF WORK PERFORMED:**

-The Fillvalve membrane was torn. I replaced this membrane and tested. -The kitchen faucet spray head has failed internally, causing the alternate spray button to malfunction. Unfortunately this head will have to be replaced.

QTY.	CODE		UNIT PRICE	PRICE		
1		Replace Porcher Fillvalve	ce Porcher Fillvalve Membrane			
invoice and tell us how we did.		warrai	ITY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00	
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45	
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  EST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$135.45	
		we did. MADE	EST AT THE LEGAL KATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND RIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN.			

<u> Thank You!</u>

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2019-05-14

CUSTOMER SIGNATURE

DATE