

(B) @SimplyPlumbing | | YaletownPlumbing



HST #837181627

DATE 2019-05-22	TECHNICIAN Darren Mann		JOB/O 9411	RDER #	REFERENCE TEXT Client reference
FIRST NAME Morvarid		LAST NAME Aletomeh			
BILLING ADDRESS COMPANY / BILLING NAME 1107 - 583 BEACH CR VANCOUVER, V6Z 3E6 BRITISH COLUMBIA, CANADA		<u></u>	SERVICE ADDRESS 1107 - 583 BEACH CR , BUZ#1086 MARIKA(TENANT): 604.787.4726 VANCOUVER, V6Z 3E6 BRITISH COLUMBIA, CANADA		26
PHONE 1.310.926.6276				EMAIL morvarid.aletomeh@gmail.com	

REASON FOR TODAY'S CALL:

Tub spout diverter not working.

DESCRIPTION OF WORK PERFORMED:

-I was able to reassemble the existing tub spout diverter parts that had come apart. Tested and in good working order. -During testing I noticed the tub drain stopper would not stay open. I replaced the tub drain trim with a new lift & turn style drain and tested.

QTY.	CODE		UNIT PRICE	PRICE	
1		Replace Tub Drain Trim - Standard			\$159.00
<i>Q.</i>	(1	and Lack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$166.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE