

HST #837181627

DATE 2019-07-09	TECHNICIAN Darren Mann		JOB/O 9510	RDER #	REFERENCE TEXT Client reference
FIRST NAME Julia		LAST NAME Kim			
BILLING ADDRESS COMPANY / BILLING NAME 1206 - 1221 BIDWELL STREET VANCOUVER, V6G 0B1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  606 - 161 WEST GEORGIA ST RYAN: 1.203.605.6232 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.418.1060				EMAIL julia786@yahoo.ca	

## REASON FOR TODAY'S CALL:

Tub spout diverter malfunctioning.

## DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with new and tested.

## TECHNICIAN RECOMMENDATIONS:

I noticed while onsite that the tub drain trim is corroding. It is possible that someone st some point either put drain clear in the tub or used a harsh cleaner on it. This drain should be replaced.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.0
<i>Q</i>		eedback warranty: Parts - Subject to Manufacturer's warranty	SUBTOTAL:	\$159.0
	t our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.9
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.			TOTAL:	\$166.9

<u> Thank You!</u>

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2019-07-09 CUSTOMER SIGNATURE DATE