



HST #837181627

DATE 2019-08-13	TECHNICIAN Darren Mann		JOB/ORDER # 9595		REFERENCE TEXT Client reference
FIRST NAME Cathy		LAST NAME Harrison	7		
BILLING ADDRESS COMPANY / BILLING NAME 807 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 807 - 1255 SEYMOUR ST JACK DUNPHY: 604.704.9203 BREANNE(GIRLFRIEND): 778 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.340.6655	-			EMAIL cathy.harrison@gmail.com	

REASON FOR TODAY'S CALL:

Tub spout diverter not working.

DESCRIPTION OF WORK PERFORMED:

The tub spout diverter was broken internally. I replaced the tub spout with a new Delta pull-down type diverter spout and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.95
			TOTAL:	\$166.95
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT, VALUES AND MATERIALS LISTED HEREON ARE CORRECT. VALUES AND AND COTHER DAYS OF THE PLANT OF THE P	KEN,	

CUSTOMER SIGNATURE

DATE