



HST #837181627

DATE 2019-08-15	TECHNICIAN Darren Mann		JOB/ORDER # 9594	REFERENCE TEXT Client reference	
FIRST NAME Liz		LAST NAME Mayer			
BILLING ADDRESS COMPANY / BILLING NAME 411 - 5605 HAMPTON PL VANCOUVER, V6T2H2 BRITISH COLUMBIA, CANADA			SERVICE ADDRES 411 - 5605 HAMPT VANCOUVER, V61 BRITISH COLUMB	ON PL 72H2	
PHONE 778.384.2146			EMAIL ejmayer@gmail.com	m	

REASON FOR TODAY'S CALL:

Something has fallen in the garburator

DESCRIPTION OF WORK PERFORMED:

-I removed a tea spoon and bits of what appeared to be coffee beans from within the grinding chamber. Tested by filling and draining the sink while running the garburator.

TECHNICIAN RECOMMENDATIONS:

The dishwasher drain hose is too short to meet the garburator drain outlet so it is kinked. I recommend extending this drain hose to get rid of this kink.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	11	Labour			\$109.00	\$109.00
		NTY: PARTS - SUBJECT TO MANUFACTU	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.			\$5.45	
					\$114.45	
		- IN	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2019-08-15

CUSTOMER SIGNATURE

DATE