

HST #837181627

DATE 2019-08-21	TECHNICIAN Darren Mann		JOB/ORDER # 9616	REFERENCE TEXT Client reference
FIRST NAME ALEX		LAST NAME YANG		·
BILLING ADDRESS COMPANY / BILLING NAME 1102 - 1050 BURRARD ST VANCOUVER, V6Z2S3 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  1808 - 788 HAMILTON ST SIDNEY: 604.250.3920 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.700.2671			EMAIL alexuoca@gmail.cor	m

REASON FOR TODAY'S CALL:

Tub/shower diverter not working.

## DESCRIPTION OF WORK PERFORMED:

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	1	Replace Standard Tub Spout Diverter	\$159.00	\$159.00
<i>Q.</i>	we us feedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			\$159.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.95
			TOTAL:	\$166.95
		We did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED RUSTED DETERIORATION OR LEAD PIPES FIXTURES OF EAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

2019-08-21

DATE