



2019-10-11

DATE

HST #837181627

DATE 2019-10-11	TECHNICIAN Darren Mann		JOB/O 9702	RDER #	REFERENCE TEXT Client reference
FIRST NAME Panan		LAST NAME Xu			
BILLING ADDRESS COMPANY / BILLING NAME 902 - 1408 STRATHMORE MEWS VACOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 902 - 1408 STRATHMORE MEWS BALAZS(TENANT): 778.887.7234 BALAZS.VEGVARI@GMAIL.COM VACOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA	
PHONE 778.688.6682				EMAIL panxu1123@gmail.com	

REASON FOR TODAY'S CALL:

Building manager claimed that is a leak running from the toilet into the ceiling in unit 802 lower floor. The location of the leak strongly suggests (in 99% of the occurrences) it is caused by a faulty wax seal in the en-suite bathroom of the unit. Please assess the wax seal and related piping beneath the toilet. *no buz, call.

DESCRIPTION OF WORK PERFORMED:

I lifted the toilet and found the wax seal to be compromised. I re-set the toilet with a new Maxwax wax ring, supply line, and tee bolts. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	7,	Replace Toilet Wax Seal - Standard	\$189.00	\$189.00
<i>Q</i>	SUBTOTAL:	\$189.00		
	t our feedbac	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.45
	ownplumbing equired detail	Com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$198.45
	tell us how w	We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE