

HST #837181627

DATE 2019-11-28	TECHNICIAN Darren Mann		JOB/ORDER # 9803	REFERENCE TEXT Client reference	
FIRST NAME David		LAST NAME Yang			
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND S' VANCOUVER, V6B2T4 BRITISH COLUMBIA, CA		2	SERVICE ADDRESS 3101 - 111 WEST GEO ROBERT: 1.971.200.00 VANCOUVER, BRITISH COLUMBIA, O	094	
PHONE 778.988.8470		EMAIL PMVan1@rentitfurnishe	EMAIL PMVan1@rentitfurnished.com		

REASON FOR TODAY'S CALL:

Tub shower diverter not working.

DESCRIPTION OF WORK PERFORMED:

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
invoice and tell us how we did. MADE THAT MATERIALS SETTLED, F RESULTING		warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
		k page at: Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
		s from your	TOTAL:	\$166.95
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	S	

CUSTOMER SIGNATURE

2019-11-28

DATE