

HST #837181627

DATE 2019-12-05	TECHNICIAN Darren Mann		JOB/ORDER # 9816	REFERENCE TEXT 19-1745	
FIRST NAME Advent		LAST NAME Admin		·	
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2103 - 989 BEATTY ST, BUZ#3103 PARV: 604.726.2685 CORA_GOODMAN@HOTMAIL.COM VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478			EMAIL andrea@adventvanco	EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Kitchen faucet: leak from the top part of the sink. Master bathroom: bathtub does not hold water as it slowly leaks out

DESCRIPTION OF WORK PERFORMED:

-The tub was not holding when. I replaced the tub drain trim and tested by filling the tub 8? and draining. -The kitchen faucet was leaking from under the handle. I removed the handle and found the nut that secures the cartridge in place to be loose. I tightened this nut and tested.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	//.	Replace Tub Drain Trim - Standard			\$159.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank Youl		Soud and	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	GST (5%):	\$7.95
				TOTAL:	\$166.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

2019-12-05