





HST #837181627

DATE 2012-08-16	TECHNICIAN darren mann			REFERENCE TEXT Client reference	
FIRST NAME Patrick		LAST NAME McCleery			
BILLING ADDRESS COMPANY / BILLING NAME #201 - 1736 WEST 10TH AVE BUZ#201 VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1736 WEST 10TH AVE BUZ#201 VANCOUVER, BRITISH COLUMBIA, CANADA			
PHONE 604.727.9175			EMAIL patrickmccleery@me	e.com	

REASON FOR TODAY'S CALL:

-tub faucet continues to run even when faucet turned to the OFF position

DESCRIPTION OF WORK PERFORMED:

-replaced shower valve cartridge in guest tub/shower. -made adjustment to the tub spout diverter.

TECHNICIAN RECOMMENDATIONS:

-when tub/shower diverter pulled down and shower activated, turn water off to res-set, do not push the diverter back up while water running.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	1/2	Labour	\$99.00	\$99.00
1	2053003	41031285 TEMP II CART I/C	\$89.00	\$89.00
PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$188.00
invoice and tell us how we did.		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	HST (12%):	\$22.56
		com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$210.56
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

Thank You!

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2012-08-16 CUSTOMER SIGNATURE DATE