





HST #837181627

TECHNICIAN darren mann		JOB/ORDER # 690	REFERENCE TEXT Client reference	
	LAST NAME Holman			
18	9	#1506 - 33 SMITH VANCOUVER, V6	E ST BUZ#5118 B0B5	
		EMAIL mylesholman@gm	nail.com	
	darren mann	darren mann LAST NAME Holman	LAST NAME Holman SERVICE ADDRE #1506 - 33 SMITH VANCOUVER, V6 BRITISH COLUME EMAIL	LAST NAME Holman SERVICE ADDRESS #1506 - 33 SMITHE ST BUZ#5118 VANCOUVER, V6B0B5 BRITISH COLUMBIA, CANADA

REASON FOR TODAY'S CALL:

-lav faucet dripping cold. -replace k35b cartridge

DESCRIPTION OF WORK PERFORMED:

-replace cartridge in lave faucet. The original cartridge was cracked inside causing the cold water to leak through.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1	y	Labour		\$99.00	\$99.00
1		K35b cartridge		\$40.00	\$40.00
Gwe us Feedback Please visit our feedback page at:	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00		
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	HST (12%):	\$16.68	
	ownplumbing equired detail	com/feedback [1] Is from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. T AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$155.68
invoice and tell us how we did. Thank You!		we did. MAD MATI SETI RESI TERI	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.		

CUSTOMER SIGNATURE

2012-09-26