





UNIT PRICE

HST #837181627

DATE 2013-03-05	TECHNICIAN Paulo Nardi		JOB/O 1369	RDER #	REFERENCE TEXT WO#4611		
FIRST NAME Andrea		LAST NAME Ferina					
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  1255 WEST 12TH AVE VANCOUVER, BRITISH COLUMBIA, CANADA			
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com			

## REASON FOR TODAY'S CALL:

-leak in mechanical room.

## **DESCRIPTION OF WORK PERFORMED:**

-replaced relief valve, tackle pump, and expansion tank in boiler room. -after filling the sytem there were reports of radiators with no heat on the top floor, we went into these units and found the bleeder valves to be non operational. we replaced these auto air vents in units 5,7,8, and 9.

## TECHNICIAN RECOMMENDATIONS:

-while working on the system we noticed a few things; there is no Back Flow Preventer installed on the boiler, the pressure feed valve on the boiler is in need of replacement, and it is suggested that the bleeder valves on the main floor be replaced.

**DESCRIPTION** 

1	Supply & Install Relief Valve,	Supply & Install Relief Valve, Tackle Pump, and Expansion Tank		\$1,500.00
1	Replaced Auto Air Vents In Ur	Replaced Auto Air Vents In Units 5,7,8, and 9		\$250.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		SUBTOTAL:	\$1,750.00	
			HST (12%):	\$210.00
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$1,960.00

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACM MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED A	
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NO SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OR RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPII	OUTS AND ANY OTHER DAMAGES
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, CHARGES, E. & O. E.	MATERIALS AND TRUCK
	2013-03-05