

YALETOWN PLUMBING SERVICES LTD
1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2014-05-15	TECHNICIAN Darren Mann	Way.	JOB/OF 3340	RDER #	REFERENCE TEXT Client reference	
FIRST NAME Kirk		LAST NAME Washington	9			
BILLING ADDRESS COMPANY / BILLING NAME 1438 RICHARDS STREET VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  #3207 - 1438 RICHARDS STRE CONCIERGE WILL PROVIDE // VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA	ACCESS.	
PHONE 6042690224				EMAIL kirk.washington@telus.net		

## REASON FOR TODAY'S CALL:

## DESCRIPTION OF WORK PERFORMED:

Removed shells from the garburator grinding chamber and tested by filling sink 3 times and draining while running the garburator. Also flushed the dishwasher drain hose to be sure no pieces found there way into the garburator's dishwasher drain outlet.

QTY.	CODE		DESCRIPTION			
1		Labour		\$99.00	\$99.00	
Gwe us Feedback Please visit our feedback page at:	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	SUBTOTAL:	\$99.00		
			GST (5%):	\$4.95		
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!			.com/feedback [1]	TOTAL:	\$103.95	
		MATERIAL SETTLED, RESULTIN TERMS: NI	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			
			2014-05-15			
			CUSTOMER SIGNATURE DATE			

<sup>&</sup>quot;My tenant put clamshells in the garburator. The unit seems to be working (albeit LOUD), so I think it needs to be removed, emptied, and replaced."