

YALETOWN PLUMBING SERVICES LTD
1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2014-11-12	TECHNICIAN Darren Mann		JOB/ORDER # 4079		REFERENCE TEXT Client reference
FIRST NAME Lisa		LAST NAME Hoy			
BILLING ADDRESS COMPANY / BILLING NAME 602 - 1488 HORNBY STREET VANCOUVER, V6Z1X3 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  602 - 1488 HORNBY STREET BUZ#6002 VANCOUVER, V6Z1X3 BRITISH COLUMBIA, CANADA	
PHONE 604.633.0120				EMAIL lisahoy13@hotmail.com	

## REASON FOR TODAY'S CALL:

## DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with a new Badger 5. The drainage was piped incorrectly causing an "S trap", I re-piped the drainage(free of charge). -The homeowner decided it may be better to replace the toilet than repair it, we will look for a replacement.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2	\$299.00	\$299.00	
Come of Goodle of		and and	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$299.00
Gwe us Feedback Please visit our feedback page at:	<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$14.95		
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$313.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE

<sup>-&</sup>quot;Water is leaking from base of the toilet. The wax seal may be faulty." -garburator leaking.