





HST #837181627

DATE 2014-12-22	TECHNICIAN Darren Mann		JOB/ORDER # 4191	REFERENCE TEXT Client reference	
FIRST NAME Roxy		LAST NAME Liao			
BILLING ADDRESS COMPANY / BILLING NAME 1068 WEST BROADWAY VANCOUVER, V6H0A7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 809 - 1068 WEST BROADWAY BUZZER: 1920 VANCOUVER, V6H0A7 BRITISH COLUMBIA, CANADA			
PHONE 6047233658			EMAIL roxyliao@gmail.com		

REASON FOR TODAY'S CALL:

Needs inspection of shower cartridge/ might need replacement.

DESCRIPTION OF WORK PERFORMED:

I removed the trim and handle to test valve, I didn't notice any leaking but the diverter was not fully diverting water to shower. I replaced the diverter cartridge.

TECHNICIAN RECOMMENDATIONS:

If the building has reported leaks coming from the mixing/pressure balance cartridge I suggest contacting Globe Union to have a replacement cartridge sent out free

QTY.	CODE	DESCRIPTION			PRICE
1	11	Replace Tub/Shower Diverter	Replace Tub/Shower Diverter - Danze(Taju)		\$129.00
Constant Warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$129.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$135.45

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

CUSTOMER SIGNATURE

DATE