





HST #837181627

DATE 2015-02-12	TECHNICIAN Darren Mann		JOB/ORDER # 4416	REFERENCE TEXT Client reference
FIRST NAME JASON		LAST NAME WU		·
BILLING ADDRESS COMPANY / BILLING NAME 610 GRANVILLE STREET VANCOUVER`, V6C3T3 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 422 - 610 GRANVILL MARIO(TENANT): 60 VANCOUVER', V6C: BRITISH COLUMBIA	LE STREET BUZ#5022 04.726.4177 3T3
PHONE 604-710-2724			EMAIL jasonwudesu@hotma	ail.com

REASON FOR TODAY'S CALL:

-Bathtub lower faucet control lever not working. Need to be replaced/fixed. -Bathroom sink pressure is low. Need to be adjusted.

DESCRIPTION OF WORK PERFORMED:

Replaced tub spout diverter.

TECHNICIAN RECOMMENDATIONS:

I noticed the copper coming out of the wall for the spout was scratched. I siliconed around the copper to ensure that if this pipe is ever compromised and leaks it will leak into the tub and not inside the wall.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$149.00	\$149.00
WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$149.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.45
			TOTAL:	\$156.45

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-02-12

CUSTOMER SIGNATURE

DATE