





HST #837181627

DATE 2015-03-12	TECHNICIAN Darren Mann		JOB/ORDER # 4523	REFERENCE TEXT Client reference		
FIRST NAME Beidi		LAST NAME Liu				
BILLING ADDRESS COMPANY / BILLING NAME 5683 HAMPTON PLACE VANCOUVER, V6T 2H3 BRITISH COLUMBIA, CANADA			109 - 5683 HAMPTOI VANCOUVER, V6T 2	SERVICE ADDRESS 109 - 5683 HAMPTON PLACE VANCOUVER, V6T 2H3 BRITISH COLUMBIA, CANADA		
PHONE (778) 918-7276			EMAIL beidiliu0705@hotmail	EMAIL beidiliu0705@hotmail.com		

REASON FOR TODAY'S CALL:

-tank to bowl gasket. -lever handle broken.

DESCRIPTION OF WORK PERFORMED:

---Guest bathroom: I replaced the tank to bowl gasket and tank bolts. ---Master ensuite: I replaced the lever handle.

TECHNICIAN RECOMMENDATIONS:

The fillvalves in both toilets are spraying out of the top of the diaphragm when filling the tank after each flush. These fill-valves should be replaced soon.

QTY.	CODE	DESCRIPTION			PRICE
1	//	Replace Tank To Bowl Gasket - Standard			\$169.00
1		Replace Toilet Tank Lever - ADD-ON PRICING			\$29.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$198.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.90
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$207.90

CUSTOMER SIGNATURE

Thank You!

invoice and tell us how we did.

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND

2015-03-12

DATE