

Phone: 604.727.4484 yaletownplumbing.com

2015-07-10

DATE

HST #837181627

DATE 2015-07-10	TECHNICIAN Darren Mann		JOB/O 4998	RDER #	REFERENCE TEXT Client reference				
FIRST NAME Janice		LAST NAME Davis							
BILLING ADDRESS COMPANY / BILLING NAME 4469 OSLER STREET VANCOUVER, V6H 2X8 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 4469 OSLER STREET VANCOUVER, V6H 2X8 BRITISH COLUMBIA, CANADA					
PHONE 6042205874				EMAIL jmdroots@gmail.com					

REASON FOR TODAY'S CALL:

I need a repair on my toilet. It is an In-Wall Tank and Carrier Dual "Flush Geberit model No. 111.335.00.1 Water is trickling into the bowl and every 5 minutes or so there is a rush of water. The guy from Cantu who recommended you thought it might be a gasket. After flushing, the tank fills up and the water stops, except for the trickle".

DESCRIPTION OF WORK PERFORMED:

I replaced the in flush valve gasket in the wall mounted Duravit toilet closest to the back entrance.

QTY.	CODE	DESCRIPTION				PRICE
1		Replace Flush-VL	V Gasket		\$129.00	\$129.00
Gwe us Teedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		and and	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45	
		INTEDEST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$135.45	
		MADE THAT MATERIALS I SETTLED, RU RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

CUSTOMER SIGNATURE