

Phone: 604.727.4484 yaletownplumbing.com

(B) @SimplyPlumbing | | YaletownPlumbing



HST #837181627

DATE 2015-08-14	TECHNICIAN Darren Mann		JOB/ORDER # 5146	REFERENCE TEXT Client reference
FIRST NAME Henry		LAST NAME Lee		·
BILLING ADDRESS COMPANY / BILLING NAME #806 - 1318 HOMER ST VANCOUVER, BRITISH COLUMBIA, CANADA			SERVICE ADDRESS #806 - 1318 HOMER ST STEVE(TENANT): 604.836.2877 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.999.3388		EMAIL henrykklee@gmail.co	EMAIL henrykklee@gmail.com	

REASON FOR TODAY'S CALL:

-water leaking out of master bathroom shower valve handle(Kohler)

DESCRIPTION OF WORK PERFORMED:

The tub/shower valve cartridge was leaking right through the handle. I replaced the pressure balance & mixing cartridges and tested.

CHARGES. E. & O. E.

TECHNICIAN RECOMMENDATIONS:

Thank You!

While onsite Steve mentioned that the guest bathroom tub/shower was not getting very hot water. I took a look at this and found that the mixing cartridge was not functioning properly and could not be adjusted to work better. I looked in my van but did not have another set of cartridges, I will have to set up another appointment to have this work done.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridges - Kohler	\$249.00	\$249.00
0	(I	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$249.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$12.45
			TOTAL:	\$261.45

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK