

2015-11-10

HST #837181627

DATE 2015-11-10	TECHNICIAN Darren Mann		JOB/ORDER # 5485	REFERENCE TEXT Client reference
FIRST NAME Hiro		LAST NAME Yagi		
BILLING ADDRESS COMPANY / BILLING NAME 7A - 139 DRAKE STREET VANCOUVER, V6Z 2T8 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 7A - 139 DRAKE STREET BUZ#813 VANCOUVER, V6Z 2T8 BRITISH COLUMBIA, CANADA	
PHONE 604.899.2640			EMAIL hiro_tprx@yahoo.com) /

REASON FOR TODAY'S CALL:

I have a problem with the hot water coming out of the cold water tap.

DESCRIPTION OF WORK PERFORMED:

It was determined by Pacific West Plumbing that the issue with hot water crossing over into the cold lines is happening within 7A. When I arrived I felt each fixture containing a cartridge that could potentially have hot water crossing over into the cold lines and found the master tub/shower valve to be the only fixture that was hot to the touch. We have started the process of elimination by replacing the mixing & pressure balancing cartridges in the master bathroom tub/shower valve.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace Mixing & Pressure Balance Cartridges - Kohler	\$259.00	\$259.00
<i>Q.</i>		SUBTOTAL:	\$259.00	
Please visit our feedback page at: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO				\$12.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			TOTAL:	\$271.95
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES A MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR SETTLED PLISTED DETERIORATION OF LEAD PIECE STYTURES. CLEAN CUITS AND ANY OTHER	BROKEN, R DAMAGES	