

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-01-20	TECHNICIAN Darren Mann		JOB/ORDER # 5732		REFERENCE TEXT Client reference	
FIRST NAME Bill		LAST NAME Runnals	7			
BILLING ADDRESS COMPANY / BILLING NAME 850 BURRARD STREET, SUITE 1005 VANCOUVER , V6Z 2J1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #1005 - 850 BURRARD STREET, SUITE 1005, BUZZER 068 *BUZZER ONLY GAINS ACCESS TO LOBBY, BILL WILL COME DOWN. VANCOUVER , V6Z 2J1 BRITISH COLUMBIA, CANADA		
PHONE 604-688-5510				EMAIL billrunnals@hotmail.com		

REASON FOR TODAY'S CALL:

The generic (Chinese?) mixer faucet is dripping, failed cartridge? The cut-off valves for the faucet are easily accessible in the empty under-sink cabinet. The toilet tank is very slow to refill. 10 minutes or more.

DESCRIPTION OF WORK PERFORMED:

-I could not remove the handle of the lavatory faucet so the cartridge cannot be replaced. -I replaced the toilet fillvalve. I had to install the tank lid at an angle because it was catching on the fillvalve lift arm.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1	1.	Replace toilet FillV	\$149.00	\$149.00	
Run of Toodle al			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
	t tell us how v		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		