



HST #837181627

DATE 2016-03-28	TECHNICIAN Darren Mann		JOB/ORDER # 5985		REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin	7		
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 504 - 1238 RICHARDS ST CHRISTINA: 778.316.3690 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279			EMAIL info@easyrent.ca		

REASON FOR TODAY'S CALL:

shower won't turn off

DESCRIPTION OF WORK PERFORMED:

The shower valve cartridge(Tempress ii) had broken internally. I replaced this cartridge and tested.

TECHNICIAN RECOMMENDATIONS:

While onsite the tenant mentioned that the tub spout was not switching back from shower to tub. I tried to repair this but it is completely seized up. It will have to be replaced.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II	\$199.00	\$199.00
<i>Q</i>	a	SUBTOTAL:	\$199.00	
_	it our feedbac	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		s from your	TOTAL:	\$208.95
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

	2016-03-28
CUSTOMER SIGNATURE	DATE