

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-04-13	TECHNICIAN Darren Mann		JOB/ORDER # 6020		REFERENCE TEXT Client reference	
FIRST NAME Brook		LAST NAME Jones	7			
BILLING ADDRESS			1.	SERVICE ADDRESS		
909 - 822 HOMER ST. VANCOUVER, V6B 6M3 BRITISH COLUMBIA, CANADA			9	#909 - 822 HOMER ST., BUZZER N/A JESSICA: 604.825.2849 MALISSA: 778.241.1409 VANCOUVER, V6B 6M3 BRITISH COLUMBIA, CANADA		
PHONE 604.809.0563	-			EMAIL brook.jones@gmail.com		

REASON FOR TODAY'S CALL:

my tenant has reported a leak around the bathtub faucet. She says: The master bathroom shower is leaking. It is leaking between the bathtub head and the wall.

## DESCRIPTION OF WORK PERFORMED:

-The first appointment scheduled was unfortunately missed by the tenant. -On the second visit I replaced the tub spout with a Delta pull-down tub spout diverter. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	1.	Appointment No Show	\$50.00	\$50.00
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
0	Concerts - Subject to MANUFACTURER'S WARRANTY			
<b>Gwe us Jeedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$10.45
			TOTAL:	\$219.45
		VE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTI ED. RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN QUITS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

2016-04-13

DATE