

HST #837181627

DATE 2016-05-06	TECHNICIAN Darren Mann		JOB/ORDER # 6102	REFERENCE TEXT Client reference
FIRST NAME Jacqueline		LAST NAME Ott	7	
BILLING ADDRESS COMPANY / BILLING NAME 2005 - 1500 HORNBY ST VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2005 - 1500 HORNB BUZZER: 3085 VANCOUVER, V6Z 2 BRITISH COLUMBIA	Y ST PR1
PHONE 778.388.6778			EMAIL jacquelineott@shaw.	ca

REASON FOR TODAY'S CALL:

-Ensuite bathroom toilet runs water after flushing. -The kitchen faucet runs cold water with a light white film in it. -Guest bathroom toilet bowl not filling properly after

DESCRIPTION OF WORK PERFORMED:

-The kitchen faucet aerator is causing the water to look milky but the air bubbles quickly dissipate. -The master bathroom float arm was rubbing against the back wall of the tank. I shorted the brass float arm and added a slight curve to it. Tested and in good working order. -The guest bathroom toilet requires a conversion kit(84499) this will be ordered and installed in a separate visit.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Labour			\$109.00	\$109.00
		/ARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$109.00	
				GST (5%):	\$5.45	
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		TOTAL:	\$114.45	
		MADE THAT S	ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

> 2016-05-06 CUSTOMER SIGNATURE

DATE