

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2016-05-26	TECHNICIAN Darren Mann		JOB/O 6179	RDER #	REFERENCE TEXT Client reference
FIRST NAME Colin		LAST NAME Doig	7		
BILLING ADDRESS RE/MAX CREST REALTY WESTSIDE 1428 WEST 7TH AVE VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA		$\sim$	4	SERVICE ADDRESS 1505 - 480 ROBSON ST BUZ#2616 ROSS: 778.628.9418 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.417.9003				EMAIL colin@colindoig.com	

**REASON FOR TODAY'S CALL:** 

-Tub/shower diverter broken. -Shower cartridge works but handle turns past the off position. -garburator not working.

## DESCRIPTION OF WORK PERFORMED:

-The tub spout diverter spool came apart inside the spout. I removed the spool, re-assemble the pieces, installed and tested. Diverter spout working as normal. -I unjammed the garburator and tested by filling and draining the sink while running the garburator. - I replaced the mixing and pressure balance cartridges in the shower valve and tested.

QTY. CODE		DESCRIPTION		PRICE	
1	Replace Mixing & Pressure Balance Cartridge - HC180				
Que e C		ANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00	
<b>Gwe us Feedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS I MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOL		\$9.95	
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$208.95	
		DE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES TERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOI TIELD, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHE SULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>RMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TR ARGES, E. & O. E.	R BROKEN, R DAMAGES		
		2016-0	5-26		
		CUSTOMER SIGNATURE DAT	E		