



DATE 2016-10-03	TECHNICIAN Darren Mann	JOB/ORDER # 6569	REFERENCE TEXT Client reference
FIRST NAME Judy		LAST NAME Sewell	
BILLING ADDRESS COMPANY / BILLING NAME 1501 - 1005 BEACH AVE BUZ#1166 VANCOUVER, V6E3W2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1501 - 1005 BEACH AVE BUZ#1166 VANCOUVER, V6E3W2 BRITISH COLUMBIA, CANADA	
PHONE 604.687.6274 (home)		EMAIL judysewell@shaw.ca	

REASON FOR TODAY'S CALL:  
Tub diverter not working.

DESCRIPTION OF WORK PERFORMED:  
The tub spout diverter became detached internally. I removed the diverter mechanism and re-installed. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
SUBTOTAL:				\$109.00
GST (5%):				\$5.45
TOTAL:				\$114.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-10-03

CUSTOMER SIGNATURE

DATE