

HST #837181627

DATE 2016-10-13	TECHNICIAN Darren Mann		JOB/ORDER # 6598	REFERENCE TEXT Client reference	
FIRST NAME David		LAST NAME Song			
BILLING ADDRESS COMPANY / BILLING NAME 2403 - 1005 BEACH AVE VANCOUVER, V6E 3W2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2403 - 1005 BEACH AVE, BUZZER 1203 VANCOUVER, V6E 3W2 BRITISH COLUMBIA, CANADA		
PHONE 604.652.2840			EMAIL Ds_01@live.ca		

REASON FOR TODAY'S CALL:

Grohe bathtub spout is slowly dripping water. The Grohe cartrdige needs to be changed possibly.

DESCRIPTION OF WORK PERFORMED:

-When I arrived onsite the tub spout did not appear to be dripping. I let David know that the water he noticed dripping out of the spout could have been from the standing water in the shower head piping slowly dripping out, he decided to go ahead with the cartridge replacement anyway. -I replaced the Grohe 47678000

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Shower Cartrid	eplace Shower Cartridge - Grohe 47678000		\$229.00
e _{mo}	(1	warr	ANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$229.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$11.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$240.45
		INT	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED AROVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u>Thank You!</u>

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

