



HST #837181627

DATE 2016-10-12	TECHNICIAN Darren Mann		JOB/ORDER # 6605		REFERENCE TEXT 16-1353	
FIRST NAME Advent		LAST NAME Admin				
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1001 - 480 ROBSON ST, BUZ#2112 LENKA: 778.858.4334 604.664.4435 VANCOUVER, BRITISH COLUMBIA, CANADA			
PHONE 604.736.6478			EMA andr	.IL ea@adventvancouver.com		

REASON FOR TODAY'S CALL:

Shower: Knob is no longer operative, cannot turn on shower

DESCRIPTION OF WORK PERFORMED:

The tub/shower valve cartridge was stripped and the handle would not turn it. I replaced the mixing and pressure balance cartridges within the valve and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	/	Replace Mixing & Pressure Balance Cartridge - HC180	\$199.00	\$199.00
invoice and tell us how we did. MADE THAT MATERIALS. SETTLED, R RESULTING TERMS: NET		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$9.95
		s from your	TOTAL:	\$208.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE

DATE