



2016-10-14 DATE

HST #837181627

| DATE 2016-10-14 | TECHNICIAN Darren Mann | | JOB/ORDER # 6602 | REFERENCE TEXT Client reference |
|---|---------------------------|-----------------------------|---|---------------------------------|
| FIRST NAME Julie | | LAST NAME Robinson | | |
| BILLING ADDRESS COMPANY / BILLING NAME 1408 - 1500 HORNBY ST. VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA | | | SERVICE ADDRESS 1408 - 1500 HORNBY BUZ2118 VANCOUVER, V6Z 2F BRITISH COLUMBIA, | R1 |
| PHONE 604.803.2393 | | EMAIL julie.robinson@gov.bc | EMAIL julie.robinson@gov.bc.ca | |

REASON FOR TODAY'S CALL:

The bathtub faucet is broken- it is impossible to get the right temperature as it just turns and turns. It can't be turned off completely- it constantly trickles.

DESCRIPTION OF WORK PERFORMED:

| QTY. | CODE | DESCRIPTION | UNIT PRICE | PRICE |
|--|------|--|------------|----------|
| 1 | // | Replace Mixing & Pressure Balance Cartridges - Kohler | \$259.00 | \$259.00 |
| <i>Q</i> | (I | WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | SUBTOTAL: | \$259.00 |
| Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You! | | k page at: Labour - 1 Year ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO | GST (5%): | \$12.95 |
| | | s from your | TOTAL: | \$271.95 |
| | | INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY | | |