

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2016-12-02	FECHNICIAN Darren Mann		JOB/ORDER # 6759		REFERENCE TEXT Client reference	
FIRST NAME Sharon		LAST NAME Westler	7			
BILLING ADDRESS COMPANY / BILLING NAME 806 - 1438 RICHARDS ST. VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 806 - 1438 RICHARDS ST., BUZZER 1055 VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA		
PHONE 604.209.4470				EMAIL Westler27@yahoo.ca		

REASON FOR TODAY'S CALL:

Toto toilet issues. After flushing it is slow to fill and the handle must be jiggled on occasion to start the tank filling.

## DESCRIPTION OF WORK PERFORMED:

The overflow hose was rubbing against the FillValve float arm, causing the FillValve to stick and not properly fill the tank after each flush. I repositioned the overflow supply hose and adjusted the height of the float as it was set a little low. Tested and in good working order.

<b>QTY</b> .	CODE	DESCRIPTION				UNIT PRICE	PRICE
1		Labour	7			\$109.00	\$109.00
0	a	and had	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$109.00
<b>Gwe us Feedback</b> Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		GST (5%):	\$5.45	
		INTEREST AT		TOTAL:	\$114.45		
<u>Tha</u>	<u>nk You</u>	<u>u!</u>	SETTLED, RU RESULTING F	ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A remot CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE & O. E. CUSTOMER SIGNATURE	ND ANY OTHER DAMAGES		