

HST #837181627

DATE 2016-12-15	TECHNICIAN Darren Mann		JOB/ORDER # 6802	REFERENCE TEXT Client reference
FIRST NAME Shuyu Michelle		LAST NAME Huang		
BILLING ADDRESS COMPANY / BILLING NAME 1007 - 1723 ALBERNI ST VANCOUVER, V6G3G9 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1007 - 1723 ALBERNI ST BUZZER: 337 VANCOUVER, V6G3G9 BRITISH COLUMBIA, CANADA	
PHONE 778.316.6161			EMAIL Michellehuang73@gm	ail.com

REASON FOR TODAY'S CALL:

We turn off the fauset for the bath tub , but the water is still dripping !

DESCRIPTION OF WORK PERFORMED:

The cartridge within the tub/shower valve failed. I replaced this cartridge with new and tested. *The Integral stops were in good working order and did not require

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE		
1		Replace Shower Cartridge - Delta	\$199.00	\$199.00		
invoice and tell us how we did. MADE THAM MATERIALS SETTLED, F RESULTING		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00		
		k page at: LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.95		
			TOTAL:	\$208.95		
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY				

CUSTOMER SIGNATURE

DATE

CHARGES. E. & O. E.