

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

| DATE<br>2017-01-04   | TECHNICIAN<br>Darren Mann |                     | JOB/ORDER #<br>6845 |   | REFERENCE TEXT<br>Client reference |
|--|---------------------------|---------------------|---------------------|---|------------------------------------|
| FIRST NAME<br>Ross   |                           | LAST NAME<br>Nelson |                     |   |                                    |
| BILLING ADDRESS<br>COMPANY / BILLING NAME<br>1975 PENDRELL STREET<br>VANCOUVER, V6G1T6<br>BRITISH COLUMBIA, CANADA |                           |                     | 4                   | SERVICE ADDRESS  #111 - 1975 PENDRELL STRE VANCOUVER, V6G1T6 BRITISH COLUMBIA, CANADA | ,                                  |
| PHONE<br>6046887677  |                           |                     |                     | EMAIL<br>tucker23@shaw.ca   |                                    |

## REASON FOR TODAY'S CALL:

Hi, I think the ring might need replacing in my toilet. It kind of springs a leak on the floor when it is flushed. It's the original toilet in this 1955 building. I realize you're not booking until the new year, but I hope you can schedule me at some point. Not a big bathroom in which to work. There is parking for your truck.

## DESCRIPTION OF WORK PERFORMED:

The leak was coming from between the tank and the bowl. When flushed, water would leak through the tank to bowl gasket down to the floor on the right side, and due to the grade of the floor, would flow to the left side. I removed the tank and re-installed with a new tank to bowl gasket, tank bolts, and supply line. Tested and in

| QTY.   | CODE                         | DESCRIPTION   | UNIT PRICE             | PRICE    |
|--|------------------------------|---|------------------------|----------|
| 1  | //,                          | Replace Tank To Bowl Gasket - Standard  | \$169.00               | \$169.00 |
| <i>Q.</i>  |                              | WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  | SUBTOTAL:              | \$169.00 |
| Gwe us Feedback Please visit our feedback page at: |                              | ck page at:  Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTE                   | GST (5%):              | \$8.45   |
|  | ownplumbing<br>equired detai | Com/feedback   1  | TOTAL:                 | \$177.45 |
| Thank You!   |                              | WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BE | O<br>ROKEN,<br>NAMAGES |          |

CUSTOMER SIGNATURE

2017-01-04