

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2017-01-04	TECHNICIAN Darren Mann		JOB/ORDER # 6866	REFERENCE TEXT Client reference	
FIRST NAME Vera		LAST NAME Sal			
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA			3208 - 1239 WEST HARRY: 604.379.7 VANCOUVER,	SERVICE ADDRESS  3208 - 1239 WEST GEORGIA ST HARRY: 604.379.7475 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.9100			EMAIL vera@rentitfurnishe	ed.com	

## REASON FOR TODAY'S CALL:

garburator not working \*call when en route(10 mins)

## DESCRIPTION OF WORK PERFORMED:

The garburator was completely seized up and there were cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining both sides of the sink multiple times while running the garburator. \*There was some water staining under the ptrap so I tightened the union connection and noticed no water seepage during testing.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//,	Supply & Install 1/2HP Badger5 Garburator	\$309.00	\$309.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$309.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$15.45
			TOTAL:	\$324.45
		We did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLE DESCRIPTION OF LAND DIFFE SHAPE OF THE PROPERTY OF THE P		

2017-01-04