

Phone: 604.727.4484 yaletownplumbing.com

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

## HST #837181627

| DATE   | TECHNICIAN  |                         | JOB/ORDER #  | REFERENCE TEXT                  |  |  |
|--|-------------|-------------------------|--|---------------------------------|--|--|
| 2017-01-20   | Darren Mann |                         | 6923   | Client reference                |  |  |
| FIRST NAME<br>Shella   |             | LAST NAME<br>Evangelsta |  | · · · · ·                       |  |  |
| BILLING ADDRESS<br>COMPANY / BILLING NAME<br>312 - 2055 YUKON ST<br>VANCOUVER, V5Y 4H9<br>BRITISH COLUMBIA, CANADA |             |                         | SERVICE ADDRESS<br>312 - 2055 YUKON ST<br>JASMIN(TENANT): 60<br>*CALL TENANT TO SI<br>VANCOUVER, V5Y 4H<br>BRITISH COLUMBIA, | 4.340.3240<br>ET UP TIME.<br>19 |  |  |
| PHONE  |             |                         | EMAIL  | EMAIL                           |  |  |
| 778.833.1749   |             |                         | sevangelista@hotmail.  | sevangelista@hotmail.com        |  |  |

REASON FOR TODAY'S CALL:

Toilet was leaking and turned off. Property manager onsite thinks it could be the wax ring seal or hand wand but not certain.

## DESCRIPTION OF WORK PERFORMED:

The ensuite toilet water supply was shut off after the leak was detected and the side spray hose was removed and installed in the guest bathroom. When I arrived I turned the water supply on to the ensuite toilet and tested by flushing a dozen times. There is no sign of moisture leaking from any of the connections and the toilet is secure with no moisture leaking from between the bowl and the floor. We went to the gym area below and saw no moisture in around the 3" drai pipe below the toilet.

| QTY.   | CODE | DESCRIPTION |  |  |    | UNIT PRICE | PRICE    |
|--|------|-------------|--|--|----|------------|----------|
| 1  |      | Labour      |  |  |    | \$109.00   | \$109.00 |
| <b>Gwe us Feedback</b><br>Please visit our feedback page at:   |      |             | WARRANTY:  | PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | 01 | SUBTOTAL:  | \$109.00 |
|  |      |             | ALROUR 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF<br>MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO<br>WARRANTY ON CUSTOMER SUPPLIED MATERIALS. |  |    | GST (5%):  | \$5.45   |
| www.yaletownplumbing.com/feedback [1]<br>Fill in the required details from your<br>invoice and tell us how we did.<br>Thank You! |      | TOTAL:      |  |  |    | \$114.45   |          |
|  |      |             |  |  |    |            |          |