

HST #837181627

DATE 2017-01-20	TECHNICIAN Darren Mann		JOB/ORDER # 6934		REFERENCE TEXT Client reference	
FIRST NAME Deepak		LAST NAME Arora	97			
BILLING ADDRESS COMPANY / BILLING NAME 1911 - 610 GRANVILLE ST VANCOUVER, V6B6J5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 508 - 1661 ONTARIO ST BUZ; JAMIE(TENANT): 604.307.510 JCHAN@COMMONWEALTHL VANCOUVER, BRITISH COLUMBIA, CANADA	2 EGAL.COM	
PHONE 1.416.876.5407				EMAIL deepakarora2044@gmail.com		

REASON FOR TODAY'S CALL:

The issue is basically the lever does not return to a normal position after flushing and the toilet keeps on flushing until you fix it by hand.

DESCRIPTION OF WORK PERFORMED:

The flushvalve gasket was starting to warp and the flush button rods were cut a little to long. I replaced the flushvalve gasket and shortened the flush button rods. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//.	Replace FlushValve Gasket - Standrad	\$129.00	\$129.00
Para Cardlas		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
Gwe us Feedback Please visit our feedback page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.45	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			TOTAL:	\$135.45
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLISTED DETERIORATION OF LEAD PIDES. FLYTHERS OF EAN OUTS AND ANY OTHER DAMAGES.		
		2017-01-20		