



DATE 2017-02-10	TECHNICIAN Darren Mann	JOB/ORDER # 6992	REFERENCE TEXT Client reference
FIRST NAME Venus		LAST NAME Chan	
BILLING ADDRESS SUTTON WEST COAST REALTY 302 - 1028 BARCLAY STREET VANCOUVER, V6E0B1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 302 - 1028 BARCLAY STREET VANCOUVER, V6E0B1 BRITISH COLUMBIA, CANADA	
PHONE 604.761.8389		EMAIL venus@sutton.com	

REASON FOR TODAY'S CALL:
Occasionally there is water seeping from the pipe which is attached to the tank

DESCRIPTION OF WORK PERFORMED:
-The leaking was coming from the bottom of the FillValve. I removed the tank and reinstalled with a new fillvalve, tank to bowl gasket, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - TOTO Universal	\$179.00	\$179.00
1		Toto Tank To Bowl Gasket	\$15.00	\$15.00
SUBTOTAL:			\$194.00	\$194.00
GST (5%):			\$9.70	\$9.70
TOTAL:			\$203.70	\$203.70

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-02-10

CUSTOMER SIGNATURE

DATE