



2017-03-07

HST #837181627

DATE 2017-03-07	TECHNICIAN Darren Mann		JOB/ORDER # 7070		REFERENCE TEXT Client reference
FIRST NAME Ruth		LAST NAME Muller			
BILLING ADDRESS COMPANY / BILLING NAME 1050 BURRARD ST VANCOUVER, V6Z2S3 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 203 - 1330 HORNBY ST BUZZER: NONE PHONE 60432 VANCOUVER, V6Z2S3 BRITISH COLUMBIA, CANADA	
PHONE 604.328.4186				EMAIL rmuller.12@hotmail.com	

REASON FOR TODAY'S CALL:

Base of toilet bowl leaking. Photo of blue sealer surrounding leak.

DESCRIPTION OF WORK PERFORMED:

The tank to bowl gasket was worn and the bolts securing the tank to the bowl were loose and seized up, allowing water leak out of the tank to the floor. There was a blue puck in the tank so I first had to clean the tank and floor. After cleaning the area I replaced the FillValve, seat disc(flapper), and reinstalled the tank with a new tank to bowl gasket, tank bolts, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace Toilet Fillvalve, Flapper, Tank To Bowl Gasket, Tank Bolts, Supply Line	\$209.00	\$209.00
Consus Goodles		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$209.00
Gwe us Feedback Please visit our feedback page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$10.45	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			TOTAL:	\$219.45
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE