



HST #837181627

DATE 2017-04-11	TECHNICIAN Darren Mann		JOB/ORDER # 7188	REFERENCE TEXT Client reference			
FIRST NAME Lee		LAST NAME Sherlock					
BILLING ADDRESS COMPANY / BILLING NAME 203 - 1199 SEYMOUR ST VANCOUVER, V6B1K3 BRITISH COLUMBIA, CANADA	4		SERVICE ADDRI 203 - 1199 SEYM VANCOUVER, VO BRITISH COLUM	OUR ST, BUZZER 003 6B1K3			
PHONE 778.379.6552			EMAIL Lsherlock3@gma	il.com			

REASON FOR TODAY'S CALL: tub diverter not fully diverting water

DESCRIPTION OF WORK PERFORMED:

-The tub spout was not fully diverting water from the spout to the shower head. I replaced the tub spout with a new Delta pull-down type diverter spout. -During the installation of the new spout I noticed a leak emanating from the cartridges within the shower valve. I replaced the mixing & pressure balance cartridges and tested.

QII.	CODE	DESCRIPTION			PRICE
1	//	Replace Mixing & Pressure Ba	\$199.00	\$199.00	
1	1/2	Replace Standard Tub Spout I	\$69.00	\$69.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$268.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$13.40
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$281.40

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES, E. & O. E.

A. low 2017-04-11 CUSTOMER SIGNATURE